

## Message Text

CONFIDENTIAL

PAGE 01 ADDIS 02283 220751Z  
ACTION SY-05

INFO OCT-01 AF-10 ISO-00 SYE-00 /016 W  
-----075844 220756Z /11  
O 220703Z MAY 78  
FM AMEMBASSY ADDIS ABABA  
TO SECSTATE WASHDC IMMEDIATE 8465  
INFO AMEMBASSY NAIROBI IMMEDIATE

C O N F I D E N T I A L ADDIS ABABA 2283

DEPT FOR A/SY/OPS/T; NAIROBI FOR RTC FROM  
TSO TEAM ADDIS

E.O. 11652: GDS  
TAGS: ASEC  
SUBJ: LOCKOUT - MOSLER HAND CHANGE

AFTER FOLLOWING RECOMMENDED PROCEDURES FOR DRILLING  
FENCE ON MOSLER 2-DRAWER WITH MOSLER HAND-CHANGE LOCK,  
IT APPEARS THAT FENCE DROPS IN WHEN TURNING DIAL STEM,  
BUT THEN CAM SEEMS TO KICK BACK THE FENCE. SUSPECT  
RELOCK. DRILLING REQUIRED 8-10 HOURS AND 15 BITS.  
PLEASE ADVISE ALTERNATIVE METHODS BY IMMEDIATE  
TELEGRAM.  
WALKER

CONFIDENTIAL

NNN

## Message Attributes

**Automatic Decaptioning:** X  
**Capture Date:** 01 jan 1994  
**Channel Indicators:** n/a  
**Current Classification:** UNCLASSIFIED  
**Concepts:** n/a  
**Control Number:** n/a  
**Copy:** SINGLE  
**Draft Date:** 22 may 1978  
**Decaption Date:** 01 jan 1960  
**Decaption Note:**  
**Disposition Action:** RELEASED  
**Disposition Approved on Date:**  
**Disposition Case Number:** n/a  
**Disposition Comment:** 25 YEAR REVIEW  
**Disposition Date:** 20 Mar 2014  
**Disposition Event:**  
**Disposition History:** n/a  
**Disposition Reason:**  
**Disposition Remarks:**  
**Document Number:** 1978ADDIS02283  
**Document Source:** CORE  
**Document Unique ID:** 00  
**Drafter:** n/a  
**Enclosure:** n/a  
**Executive Order:** GS  
**Errors:** N/A  
**Expiration:**  
**Film Number:** D780214-1372  
**Format:** TEL  
**From:** ADDIS ABABA  
**Handling Restrictions:** n/a  
**Image Path:**  
**ISecure:** 1  
**Legacy Key:** link1978/newtext/t19780535/aaaabdiu.tel  
**Line Count:** 38  
**Litigation Code IDs:**  
**Litigation Codes:**  
**Litigation History:**  
**Locator:** TEXT ON-LINE, ON MICROFILM  
**Message ID:** bacd8a99-c288-dd11-92da-001cc4696bcc  
**Office:** ACTION SY  
**Original Classification:** CONFIDENTIAL  
**Original Handling Restrictions:** n/a  
**Original Previous Classification:** n/a  
**Original Previous Handling Restrictions:** n/a  
**Page Count:** 1  
**Previous Channel Indicators:** n/a  
**Previous Classification:** CONFIDENTIAL  
**Previous Handling Restrictions:** n/a  
**Reference:** n/a  
**Retention:** 0  
**Review Action:** RELEASED, APPROVED  
**Review Content Flags:**  
**Review Date:** 24 apr 2005  
**Review Event:**  
**Review Exemptions:** n/a  
**Review Media Identifier:**  
**Review Release Date:** n/a  
**Review Release Event:** n/a  
**Review Transfer Date:**  
**Review Withdrawn Fields:** n/a  
**SAS ID:** 2622123  
**Secure:** OPEN  
**Status:** NATIVE  
**Subject:** LOCKOUT - MOSLER HAND CHANGE AFTER FOLLOWING RECOMMENDED PROCEDURES FOR DRILLING FENCE ON MOSLER 2-DRAWER WITH MOSLER HAND-CHANGE L  
**TAGS:** ASEC  
**To:** STATE  
**Type:** TE  
**vdkgvkey:** odbc://SAS/SAS.dbo.SAS\_Docs/bacd8a99-c288-dd11-92da-001cc4696bcc  
**Review Markings:**  
Sheryl P. Walter  
Declassified/Released  
US Department of State  
EO Systematic Review  
20 Mar 2014  
**Markings:** Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014